

Tank Setup (from left to right)

4x2.5 Suction Screen - 2015-018

2.5 ST EL 90 - BK440

MHP Charge Suction- 2.5"

2.5 CL NIP - BK 140

2.5 BV - 2017-03040

2.5 HB - FT250

3x2 Suction Screen - 2015-017

2 ST EL 90 - BK432

4.88 Suction - 2"

2 CL NIP - BK132

2 BV - 2017-03032

2 MJIC x MNPT - 2404-32-32

3x2 Suction Screen - 2015-017

2 ST EL 90 - BK432

4.88 Suction - 2"

2 CL NIP - BK132

2 BV - 2017-03032

2 MJIC x MNPT - 2404-32-32

3x2 Suction Screen - 2015-017

2 ST EL 90 - BK432

4.88 Suction - 2"

2 CL NIP - BK132

2 BV - 2017-03032

2 MJIC x MNPT - 2404-32-32

3x2 Suction Screen - 2015-017

2 ST EL 90 - BK432

3.88 Suction - 2"

2 CL NIP - BK132

V20 Suction - 1.25"

2 BV - 2017-03032

2 CL NIP - BK132

2 T - BK832

2 ST EL 90 - BK432

2 ST EL 90 - BK432

2 MJIC x MNTP - 2404-32-32

1.25 MJIC x MNTP - 2404-20-32

4x2 Bushing - BK33264

2 CL NIP - BK1332

2 BV - 2017-03032

Tandem 3.0 Suction - 1.25"

2 HB x MNPT - FT200

Single 3.0 - 1.25"

ORF - 32-90

Filter Base - 2015-026

2 ST EL 90 - BK432

2 CL NIP - BK1332

2 BV - 2017-03032

2 CL NIP - BK1332

2 T - BK832

2 ST EL 90 - BK432

2 MJIC x MNPT - 2404-20-32

Oil Tank Low Oil Alert

2001-0275 - LS1900

BK30408 - .25" x .5" Bushing

BK108x384 - .5" x 24" Nipple

(2) BK30816 - .5" x 1" Bushing

BK408 - .5" ST EL 90

2001-0335 - .25" Strain Relief

BK31632 - 1" x 2" Bushing

BK208 - .5" Coupler