


#1407, 1408, 1409, 14011

4RPTA



REASONING

421 54 GPM Reduce To 38

50-50 SPLIT C 19 19

Ratio's	Windmills	Handston
12-30	Prim RPM 78	82
14-29	Sec 138	145
17-54	Dev 73	77
12-24	Cross 117	92

Plumb For RT HAND OR L HAND